

## INSTALLATION INSTRUCTIONS

No. 541, No. 541N

Attach the universal crossbar to the junction box with the 8-32 screws. Note the crossbar can be rotated to orient the brass thumbturns.

Attach the leads to the socket.

Align the socket keyhole openings, small ends, over the 3.5" c-c tapped holes in the crossbar.

Attach the socket using the threaded rods as far as the stop nuts.

Slip the fixture over the rods and secure with the brass thumbturns. Do not overtighten.

Install the light bulb and glass shade.

## SPECIFICATIONS

Junction box: octagonal metal or round plastic, attachment holes 3.5" c-c, 8-32 tapped. The universal crossbar can accommodate other types as well. Other sized screws may be required.

Socket: E26

Maximum wattage: 60W, 110-240 volts

Base diameter: 5.5"

Projection: 7.25"

Projection of No. 541N with glass globe: 7"

Weight of all components: 2.5 lbs

To be installed by a licenced electrician.

